

ਵੱਲੋਂ

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ:1 ਭ ਤੇ ਮ ਸਾਖਾ,
ਸੰਗਰੂਰ।

ਵੱਲ

ਪ੍ਰਿੰਸੀਪਲ
ਸੰਤ ਅਤਰ ਸਿੰਘ ਅਕਾਲ ਅਕੈਡਮੀ
ਗੁਰਸਾਗਰ ਮਸਤੂਆਣਾ ਸਾਹਿਬ (ਸੰਗਰੂਰ)।

ਨੰਬਰ 82

ਮਿਤੀ 26-05-2022

ਵਿਸ਼ਾ

ਸਾਲ 2022-23 ਦੇ ਲਈ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ।

ਹਵਾਲਾ:

ਆਪ ਜੀ ਦਾ ਪੱਤਰ ਨੰ: A/SASAA/2022/NOC-642, ਮਿਤੀ 02-05-2022

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਸਬੰਧੀ ਹਵਾਲਾ ਅਧੀਨ ਪੱਤਰ ਰਾਹੀਂ ਪ੍ਰਾਪਤ ਹੋਇਆ ਕੇਸ ਲੋੜੀਂਦੀ


ਇੰਸਪੈਕਸ਼ਨ ਕਰਨ ਉਪਰੰਤ ਸਮੇਤ ਸਰਟੀਫਿਕੇਟ ਆਪ ਜੀ ਨੂੰ ਅਗਲੇਰੀ ਯੋਗ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ

ਜਾਂਦਾ ਹੈ ਜੀ। ਲੋੜੀਂਦੀ ਇੰਸਪੈਕਸ਼ਨ ਫੀਸ ਬਾਬਤ ਰੁਪਏ 5000/- ਜੀ.ਆਰ ਨੰ: 152466 ਮਿਤੀ

26-5-2022

ਰਾਂਹੀ ਜਮ੍ਹਾਂ ਕਰਵਾ ਲਈ ਗਈ ਹੈ।


ਨੱਥੀ / ਸਰਟੀਫਿਕੇਟ।


ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ:1 ਭ ਤੇ ਮ ਸਾਖਾ,
ਸੰਗਰੂਰ।

ਪਿੱਠ ਅੰਕਣ ਨੰਬਰ:

ਮਿਤੀ

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ
ਭਵਨ ਤੇ ਮਾਰਗ ਸਾਖਾ, ਸੰਗਰੂਰ ਜੀ ਨੂੰ ਆਪ ਜੀ ਦੇ ਪਿੱਠ ਅੰਕਣ ਨੰ: 882, ਮਿਤੀ 05-05-2022 ਦੇ
ਹਵਾਲੇ ਵਿੱਚ ਸੂਚਨਾ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।


ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ:1 ਭ ਤੇ ਮ ਸਾਖਾ,
ਸੰਗਰੂਰ।


Part-II

Building Safety Report

Name of School: Sant Attar Singh Akal Academy, Gursagar Mastuana
Sahib, (Distt. Sangrur).

I have visited the above-mentioned School Building along with Sh. Gurpreet Singh / Assistant Engineer and on visually inspection; it seems visually safe subject to the following observation & conditions.

- a) Parameters to check the stability and safety of building as Architectural Drawings, Bearing capacity, Foundation detail, Structural Drawings, Technical Specifications, Test Reports of Material used, Quality Control reports and certificate from the Engineer in-Charge for construction are not available.
- b) In case any addition, alteration or expansion and modification to this building are done certificate may be obtained after the completion from the undersigned.
- c) In case the building is affected by flood or if there is any settlement of walls/ foundation or sagging of roofs etc. immediate inspection of the undersigned be arranged to check stability and safety of the building.
- d) A separate certificate regarding Fire Fighting should be obtained from the competent Authority.
- e) A separate certificate regarding Electrical works should be obtained from the competent Authority.
- f) The owner of the building / Management is fully responsible regarding safety of the building from all angles in spite of the report.
- g) The covered area of the building is As per Drawings Sft.
- h) The report is not valid for legal purpose.
- i) The building visually seems safe to occupy for normal use to **One Year, upto 31/03/2023**


Sub Divisional Engineer
Const. Sub Division No.1 PWD, B&R
Sangrur.